















INSTALLATION MANUAL








Eastbrook Code	Adjustment	Eastbrook Code	Adjustment
69.0116	840-850	69.0118	940-950
69.0119	1140-1500	69.0120	790-800






This product should only be fixed by a fully qualified installer


WI3  1X	WI14  1X	WI1  1X	WI2  2X	WI4  2X	WI5  6X
WI6  8X	WI7  8X	WI8  2X	WI9  2X		
WI10  6X	WI11  1X	WI12  1X	WI13  1X		




1




2




3




4




5




6




7




8




9




10




11




12




13



14



15



Silicone on the outside of the screen only

Cleaning & Maintenance

Don't clean the shower enclosure with irritant detergent such as alcohol,bleach or other chemical cleaners.

Only clean with warm soapy water.

After the installation is completed,should you find that there is notable noise when the glass door moves,you may add a small quantity of lubricant onto the roller wheel,slipping hook and the track.

Helpline: 01452 317890