

INSTALLATION MANUAL


Eastbrook

Eastbrook Road, Gloucester GL4 3DB
Technical Helpline: 01452 317890
email: technical@eastbrookco.com














Eastbrook Code	Adjustment	Eastbrook Code	Adjustment
69.0069	970-1000	69.0070	1070-1100
69.0071	1170-1200	69.0072	1370-1400
69.0073	1570-1600		








B532+B551



This product should only be fixed by a fully qualified installer


S01  2X	S02  1X	S03  2X	S04  1X	S05  2X	S06  16 ST4 2X
S07  3X	S08  2X	S09  1X	S10  1X	S11  17X	S12  10 ST4 13X
S13  8X	S14  30 ST4 12X	S15  2X	S18  30 ST4 4X		



Ø6




Ø3.2




L


R




1




S01




2




2.1




2.2




2.3




3



S16




4




S02

S03

4.1




S14(2X)

5



5.1




5.2





5.3

**6**


6.1





6.2

**7**


7.1




7.2

**8**



8.1





8.2




8.3

**9**


9.1

**10**


10.1





10.2





11





12



13





14




15

Silicone on the outside of the screen only



16



C l e a n i n g & M a i n t e n a n c e

Don't clean the shower enclosure with irritant detergent such as alcohol,bleach or other chemical cleaners.

Only clean with warm soapy water.

After the installation is completed,should you find that there is notable noise when the glass door moves,you may add a small quantity of lubricant onto the roller wheel,slipping hook and the track.

Helpline: 01452 317890