




Referencias	Modulos	Cotas A	Cota B
51000111-036	1	100	82
51000112-036	2	163	145
51000113-036	3	226	208
51000114-036	4	289	271
51000116-036	6	415	397



Referencias	Modulos	X min	X max
51000111-036	1		
51000112-036	2		
51000113-036	3	2	30
51000114-036	4		
51000116-036	6		

CAJAS METÁLICAS DE EMPOTRAR
CAIXAS METALICAS DE ENCASTRAR
BOÎTES METALLIQUES D'ENCASTRAMENT
FLUSH-MOUNTING METAL BOXES



INFORMACIÓN TÉCNICA / INFORMAÇÃO TÉCNICA / INFORMATION TECHNIQUE / TECHNICAL INFORMATION

Para asegurar el cumplimiento del REBT y la norma UNE-EN 60.670-1:2006 se deben instalar los productos según las presentes instrucciones. SIMON no es responsable si no se realiza bajo sus condiciones.



Para assegurar o cumprimento do REBT e a norma UNE-EN 60.670-1:2006 é necesario instalar o produto de acordo com as presentes instruções. A SIMON nao assume qualquer responsabilidades se as suas condições nao forem observadas.

Pour garantir le respect de la REBT et la norme UNE-EN 60.670-1:2006, on doit installer le produit conformément aux présentes instructions. SIMON se dégage de toute responsabilité si ces conditions ne sont pas respectées.


To ensure compliance with the low voltage electro-technical regulations and the UNE-EN 60.670-1:2006 standard, this product must be installed in accordance with the instructions provided. SIMON accepts no responsibility if these conditions are not met.

MANTENIMIENTO / MANUTENÇÃO / MAINTENANCE / ENTRETIEN


Limpiar la superficie de los envoltentes con un trapo húmedo.
 Limpiar a superfície dos envoltentes com um pano húmedo.
 Nettoyer la surface des enveloppe avec un chiffon humide.
 To clean the surfaces of envelope use an humid rag.




51000111-036
1mod




51000112-036
2mod




51000113-036
3mod




51040013-036
3mod



51000114-036
4mod



51040014-036
4mod



51000116-036
6mod

