

Our products are designed to be fitted by a fully qualified installer and in compliance with all relevant regulations.

• Eastbrook will not accept any liability for damage, injury or unsatisfactory performance if the product is not fitted by a fully qualified installer.

• Max. Working pressure : 4 bar

• We reserve to change any technical specification without prior notice.

• This product is warrantied against manufacturing defects and our liability under any

guarantee is limited to repair or replacement of the defective product. The warranty is not transferrable.

- Corrosion inhibitor must be added to the system regularly in order to maintain the warranty.
- * Radiator valves are not supplied with the radiators.

www.eastbrooktrade.com

email : technical@eastbrookco.com

Phone : 01452 317890

Cross Section

Wall mounting

apparatus

1 x Air Vent

Eastbrook

1 x Blank Plug

X4

Setscrew

(M5 X 8)

Eastbrook 🚍

CONGRATULATIONS

You are the proud owner of an exclusive Biava HV Towel Rail which has been specially produced by our craftsmen who would wish you to enjoy many years of satisfaction from it.

INSTALLATION

This product must be installed by a fully qualified engineer.

- Please consider using an Eastbrook Valve Set this will ensure that your radiator looks its best with matching radiator valves.
- On commissioning, flush the central heating system thoroughly using a proprietary solution to
 ensure that aggressive substances such as fluxes and manufacturing residue, from which internal
 surfaces of your radiator can sustain irreparable damage are removed. An appropriately
 approved corrosion inhibitor <u>must</u> be subsequently added to the heating system in order to
 protect the radiator and other parts of the central heating system to promote extended operating
 lifespan.

MAINTENANCE

- From time to time it is advisable to clean your towel rail with a warm damp cloth. Never use any form of abrasive cleaner or chemical.
- Corrosion inhibitor must also be regularly maintained, please cosult your engineer for details.

IMPORTANT

Biava HV Towel Rail is not suitable for use on direct central heating systems. Please consult your engineer or supplier.

WARRANTY

Your Biava HV Towel Rail is fully warrented for five years in respect of defective materials and workmanship and subject to installation being carried out by a qualified engineer in accordance with good practice and corrosion inhibitors being regularly maintained.

REMEMBER Excellence is worth looking after.