



W=F005	W1	W2
600+300	509	273
800+300	709	273
900+300	809	273
1100+300	1009	273

L=F005S	L1
700	642
760	702
800	742
900	842