

## **RYTON TOWEL RAIL**

# Eastbrook





Drill the holes for the wall plugs with a Ø 10 mm drill bit as illustrated in the figure.






www.eastbrooktrade.com







- We reserve to change any technical specification without prior notice.
- This product is warrantied against manufacturing defects and our liability under any guarantee is limited to repair or replacement of the defective product. The warranty is not transferrable.
- Corrosion inhibitor must be added to the system regularly in order to maintain the warranty.
- \* Radiator valves are not supplied with the radiators.

Fix the wall mounting apparatus on the wall as illustrated.











Hold the product carefully and put the panel mounting apparatus into the wall mounting apparatus and then fix it by tightening the bolts.

Wall mounting apparatus



Cross Section

#### SUPPLIED INSTALLATION ACCESSORIES



#### PLEASE READ THIS INSTRUCTION THROUGHLY BEFORE STARTING THE INSTALLATION

Our products are designed to be fitted by a fully qualified installer and in compliance with all relevant regulations.

- Eastbrook will not accept any liability for damage, injury or unsatisfactory performance if the product is not fitted by a fully qualified installer.
- Max. Working pressure: 4 bar

HELPLINE email: technical@eastbrookco.com

HELPLINE Phone: 01452 317890



#### **CONGRATULATIONS**

You are the proud owner of an exclusive Ryton Towel Rail which has been specially produced by our craftsmen who would wish you to enjoy many years of satisfaction from it.

#### **INSTALLATION**

This product must be installed by a fully qualified engineer.

- Please consider using an Eastbrook Valve Set this will ensure that your radiator looks its best with matching radiator valves.
- On commissioning, flush the central heating system thoroughly using a proprietary solution to
  ensure that aggressive substances such as fluxes and manufacturing residue, from which internal
  surfaces of your radiator can sustain irreparable damage are removed. An appropriately
  approved corrosion inhibitor <u>must</u> be subsequently added to the heating system in order to
  protect the radiator and other parts of the central heating system to promote extended operating
  lifespan.

#### **MAINTENANCE**

- From time to time it is advisable to clean your towel rail with a warm damp cloth. Never use any form of abrasive cleaner or chemical.
- Corrosion inhibitor must also be regularly maintained, please consult your engineer for details.

### **IMPORTANT**

Ryton Towel Rail is not suitable for use on direct central heating systems. Please consult your engineer or supplier.

#### **WARRANTY**

Your Ryton Towel Rail is fully warranted for five years in respect of defective materials and workmanship and subject to installation being carried out by a qualified engineer in accordance with good practice and corrosion inhibitors being regularly maintained.

**REMEMBER** ..... Excellence is worth looking after.

HELPLINE Phone : 01452 317890
HELPLINE email : technical@eastbrookco.com