

#### **OPTIONS**

#### Flush Volume

0.5 gpf (1.9 Lpf) (0.5)

1.0 gpf (3.8 Lpf) (1.0)

1.5 gpf (5.7 Lpf) (1.5)

0.125 gpf (0.5 Lpf) (0.125)

0.25 gpf (0.9 Lpf) (0.25)

### **Water Efficiency**

High Efficiency

Low Consumption

Water Saver

# **Bypass**

Dual-Filtered Fixed Bypass Diaphragm

**Dual-Filtered Bypass** 

### **Compliances & Certifications**

**ADA Compliant** 

**BAA Compliant** 

**BABAA** Compliant

**UPC** Certified

**BREEAM Water Credit** 

Green Globes Water Credit

LEED V4 Water Efficiency Credit

Satisfies LEED Credits

WaterSense Listed

cUPC Certified

# NOTES

For product line drawings, view model-specific spec sheets.

All information contained within this document subject to change without notice.



## **DESCRIPTION**

Sloan® Exposed Sensor Urinal Flushometer

#### **FEATURES**

- Flush volumes start as low as 1.0 gpf/3.8 Lpf
- Water conservation is aided by the ADA-compliant, non-holdopen handle, which prevents urinal from exceeding intended flush volume
- Flush accuracy is controlled by CID™ technology, also enhancing water efficiency
- Integrity of the product is maintained with the vandalresistant stop cap
- Durability is facilitated with high copper, low zinc brass castings for dezincification resistance
- Adjustable tailpiece to accommodate different height requirements
- High chloramine resistant PERMEX synthetic rubber diaphragm with Linear Filtered Bypass and Vortex Cleansing Action
- Valve body, Cover, Tailpiece and Control Stop shall be in compliance with ASTM Alloy Classification for Semi-Red Brass
- Valve shall be in compliance to the applicable sections of ASSE 1037.

# **DOWNLOADS**

- Sloan Exposed Installation Instructions
- Sloan Exposed (Spanish) Installation Instructions
- Optima SMO Installation Instructions
- Control Stop Repair and Maintenance Guide
- Flush Connections Flanges Repair and Maintenance Guide
- Tail Piece Repair and Maintenance Guide

Sloan 10500 Seymour Ave, Franklin Park, IL 60131

Phone: 800.982.5839 • Fax: 800.447.8329 • sloan.com



- Sloan Flushometer Repair and Maintenance Guide
- EBV-89A Side Mount Repair and Maintenance Guide
- Additional Downloads

**Sloan 10500 Seymour Ave, Franklin Park, IL 60131** Phone: 800.982.5839 • Fax: 800.447.8329 • sloan.com