

Dry Gauges



Welding Gauges, Oxygen, Bottom Connection

Part No.	Type	Case Dia.	Case	Window	Movement	Bourdon Tube	Connection	Entry	Range	Operating Temp.	Accuracy
OG50-050	DRYO2	50MM	Golden Steel	Polycarbonate	Brass	Phosphor Bronze	Brass	Bottom BSPP 1/4"	0-5kg/cm2 / Lb/in2	Ambient -20 + 60°C	2.50%
OG50-010	DRYO2	50MM	Golden Steel	Polycarbonate	Brass	Phosphor Bronze	Brass	Bottom BSPP 1/4"	0-10kg/cm2 / Lb/in2	Ambient -20 + 60°C	2.50%

