

Dry Gauges



Vacuum Gauges, Centre Back Connection

Part No.	Type	Case Dia.	Case	Window	Movement	Bourdon Tube	Connection	Entry	Range	Operating Temp.	Accuracy
VG40-01R	DRY	40MM	PLASTIC ABS	ACRYLIC	BRASS	Phosphor Bronze	BRASS	CBM BSPT 1/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG50-01R	DRY	50MM	PLASTIC ABS	ACRYLIC	BRASS	Phosphor Bronze	BRASS	CBM BSPT 1/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG050-01T	DRY	50MM	PLASTIC ABS	ACRYLIC	BRASS	Phosphor Bronze	BRASS	CBM BSPT 1/4"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG63-01T	DRY	63MM	PLASTIC ABS	ACRYLIC	BRASS	Phosphor Bronze	BRASS	CBM BSPT 1/4"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG100-01T	DRY	100MM	BLACK STEEL	ACRYLIC	BRASS	Phosphor Bronze	BRASS	CBM BSPT 3/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%

