

Dry Gauges



Vacuum Gauges, Bottom Connection

Part No.	Type	Case Dia.	Case	Window	Movement	Bourdon Tube	Connection	Entry	Range	Operating Temp.	Accuracy
VG40-01B	Dry	40MM	Plastic ABS	Acrylic	Brass	Phosphor Bronze	Brass	Bottom BSPT 1/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG50-01B	Dry	50MM	Plastic ABS	Acrylic	Brass	Phosphor Bronze	Brass	Bottom BSPT 1/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG50-01C	Dry	50MM	Plastic ABS	Acrylic	Brass	Phosphor Bronze	Brass	Bottom BSPT 1/4"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG63-01C	Dry	63MM	Plastic ABS	Acrylic	Brass	Phosphor Bronze	Brass	Bottom BSPT 1/4"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%
VG100-01D	Dry	100MM	Plastic ABS	Acrylic	Brass	Phosphor Bronze	Brass	Bottom BSPT 3/8"	-1000mbar+0 / -30 inHg+0	AMBIENT -20 + 60°C	2.50%

