


Version 1: May 2025

Read this manual in full before using this product and retain it for future use. Always use the latest version of the manual. Please visit drapertools.com/manuals for the latest version.



Identification


- A** V-shaped cable holder
- B** Adjusting nut
- C** Insulation lever
- D** Adjusting screw
- E** Body
- F** Pusher
- G** Cable diameter guide

Intended Use


Designed to strip cable sheath on cables 6 to 25mm diameter. Fitted with self locking adjustable cutting depth lever.

Instructions

1. Turn the adjusting nut **B** to get the correct exposed length of blade for the cable and blade height.



2. Turn adjusting screw **D** to get the approximate cable diameter (not critical). This diameter is indicated on cable diameter guide **G**.
3. Open the tool by pushing **F** upwards, and insert the cable between the blade and the V-shaped cable holder **A**, and release.
4. Rotate the tool 2 – 3 times in a clockwise direction, to cut round the cable.



5. Swivel the blade by pushing the shaft, and pull the stripper along the cable, to make a longitudinal cut.
6. Use the sharp edge of the insulation lever **C** to lever insulation from conductor if necessary.

Draper Tools

Draper Tools Limited
Hursley Road, Chandler's Ford
Eastleigh, Hampshire, SO53 1YF UK

Website: drapertools.com

Email: sales@drapertools.com

Product Helpline: +44 (0) 23 8049 4344

Telephone Sales Desk: +44 (0) 23 8049 4333

General Enquiries: +44 (0) 23 8026 6355

Delta International

Delta International BV
Oude Graaf 8
6002 NL
Weert
Netherlands