


Referencias	Modulos	Cotas A
51000011-036	1	81,5
51000012-036	2	144,5
51000013-036	3	207,5
51000014-036	4	270,5
51000016-036	6	396,5



Referencias	Modulos	Cotas A
51000011-036	1	43
51000012-036	2	106
51000013-036	3	149
51000014-036	4	212
51000016-036	6	332

#### INFORMACIÓN TÉCNICA / INFORMAÇÃO TÉCNICA / INFORMATION TECHNIQUE / TECHNICAL INFORMATION

Para asegurar el cumplimiento del REBT y la norma UNE-EN 60.670-1:2006 se deben instalar los productos según las presentes instrucciones. SIMON no es responsable si no se realiza bajo sus condiciones.


Para assegurar o cumprimento do REBT e a norma UNE-EN 60.670-1:2006 é necessario instalar o produto de acordo com as presentes instruções. A SIMON nao assume qualquer reaponsabilidades se as suas condições nao forem observadas.

Pour garantir le respect de la REBT et la norme UNE-EN 60.670-1:2006, on doit installer le produit conformément aux présentes instructions. SIMON se dégage de toute responsabilité si ces conditions ne sont pas respectées.

To ensure compliance with the low voltage electro-technical regulations and the UNE-EN 60.670-1:2006 standard, this product must be installed in accordance with the instructions provided. SIMON accepts no responsibility if these conditions are not met.

#### MANTENIMIENTO / MANUTENÇÃO / MAINTENANCE / ENTRETIEN


Limpiar la superficie de los envoltentes con un trapo húmedo.  
Limpiar a superfície dos envoltentes com um pano húmido.  
Nettoyer la surface des enveloppe avec un chiffon humide.  
To clean the surfaces of envelope use an humid rag.




# simon

## Simon 500 CIMA


CAJAS DE SUPERFICIE METÁLICAS  
CAIXAS DE SUPERFICIE METÁLICAS  
BOÎTES DE SURFACE MÉTALLIQUES  
METAL SURFACE MOUNTING BOXES



51000011 - 036  
1mod




51000012 - 036  
2mod




51000013 - 036  
3mod




51040013 - 036  
3mod



51000014 - 036  
4mod



51040014 - 036  
4mod



51000016 - 036  
6mod

