



INSTALLATION MANUAL









Eastbrook Code	Adjustment	Eastbrook Code	Adjustment
69.0111	660-700	69.0112	720-760
69.0113	760-800	69.0114	860-900





B67+B551




This product should only be fixed by a fully qualified installer

D01  2X	D03  13X	D04  4X	D05  8X
D06  1X	D07  17X	D09  1X	D10  4X






L





R




1




D09(1X)



D01(1X)


 $\emptyset \in$ 

D05(8X)




D10(4X)


3




4




5




6





7






8





9



10



11



Silicone on the outside of the screen only

Cleaning & Maintenance

Don't clean the shower enclosure with irritant detergent such as alcohol,bleach or other chemical cleaners.

Only clean with warm soapy water.

After the installation is completed,should you find that there is notable noise when the glass door moves,you may add a small quantity of lubricant onto the roller wheel,slipping hook and the track.

Helpline: 01452 317890